

September 19, 2020


Exhibit AA

Street view: 3200 Damascus Church Rd.

Proposed “repair” drain field

“The area of investigation was a maintained lawn” as stated by LSS Morgan

No evidence of 4’ deep back hoe pits for soil profile tests performed July 2, 2020



September 27, 2020



Proposed “repair” drain field

“The area of investigation was a maintained lawn” as stated by LSS Morgan
No evidence of 4’ deep back hoe pits for soil profile tests performed July 2, 2020

